
RAAF TAIL NO: A8-127 USAF SERIAL NUMBER: A8-127

NOTES: RAAF AIRCRAFT. Aircraft no longer in the RAAF inventory - Crashed at Guyra,

NSW on 13 Sep 1993. Hit the ground during a toss bomb manoeuvre on the Guyra

Meat Works. High wind, snowing and after dark.

A/C was a 1SQN Jet. The A/C had accrued 4471.6 AFHRs at the time of acceptance

by Aircrew.

Last R5 at 2803.5 dated 30 Sep 86 Last R4 at 3824.7 dated 24 Sep 90

Last R3 at 4349.5 dated 26 May 93 At 501WG

Killed

GD S/N: 3

Pilot: FLTLT J. D. McNESS ✓

Navigator: FLTLT M.K. CAIRNS-COWAN ✓

DATE CRASHED: 13/09/1993

ROLLOUT DATE:

LOCATION: Guyra, NSW

ACCEPTANCE DATE: MODEL-TYPE: D1

TRANSFER DATE: 6/04/1973 TYPE VERSION: F-111C

RAAF TAIL NO: A8-128 USAF SERIAL NUMBER: A8-128

NOTES: RAAF AIRCRAFT. Aircraft no longer in the RAAF inventory - Crashed approx 1.5 NM

NNE from Tenterfield, NSW on 2 April 1987. Hit ground during low day into night flying exercise. This A/C was configured with a M61-A1 gun and cargo pannier.

A/C was a 6SQN asset.

Killed

Pilot: FLTLT Mark Andrew FALLON ✓

Navigator: FLGOFF William George PIKE

DATE CRASHED: 2/04/1987

LOCATION: Tenterfield, NSW

ROLLOUT DATE: GD S/N: 4

ACCEPTANCE DATE: MODEL-TYPE: D1

TRANSFER DATE: 30/04/1973 TYPE VERSION: F-111C

RAAF TAIL	no: A8-1 3	33	USAF SERIAL NUMBER: A8-133
NOTES:	Head, NSW range. Crass failed to save Most of the M	, on 29 September, 1977, imp sh was due to at least three Bi e the crew. wreckage was buried on site. ik was a pilot under training.	e RAAF inventory - Crashed at Evans pacting the ground 16.1 kms from the rd strikes. Ejection was initiated, however
			Killed
	Pilot:	SQNLDR John HOLT	✓
	Navigator:	FLTLT Adam NOORDINK	✓
DATE	CRASHED:	29/09/1977	
	LOCATION:	Evans Head, NSW	
ROLL	OUT DATE:		GD S/N : 9
ACCEPTA	ANCE DATE:		MODEL-TYPE: D1
TRANS	SFER DATE:		TYPE VERSION: F-111C
RAAF TAIL	no: A8-1 3	36	USAF SERIAL NUMBER: A8-136
NOTES:	RAAF AIRC		to crash. ger in the RAAF inventory - Crashed at was due to Air Duct failure through fatigu
		Exchange Pilot Capt Bill Bake David Allan Clarkson	r (Billy Bang out)
	A/C crashed	one Klm off the New England	Highway 24 k NE of Armidale.
			Killed
	Pilot:	CAPT William BAKER	
	Navigator:	FLTLT David Allan CLARKS	
DATE	CRASHED:	28/04/1977	
	LOCATION:	Armidale, NSW	
ROLL	OUT DATE:		GD S/N : 12
ACCEPTA	ANCE DATE:		MODEL-TYPE: D1
TRANS	SFER DATE:		TYPE VERSION: F-111C

RAAF TAIL	NO: A8-1 3	37	USAF SERIAL NUMBER: A8-	-137
NOTES:	Base, Ohake	RAFT. Aircraft no longer in the Ra ea on 24 August, 1979. Crash wa ake off, which caused a double co	as due to water ingestion from mpression stall.	
	Dilote	FLGOFF KELLY	Killed	
	Navigator:	FLTLT CURR		
DATE	CRASHED:	24/08/1979		
	LOCATION:	Ohakea, NZ		
ROLL	OUT DATE:		GD S/N : 13	
ACCEPTA	NCE DATE:		MODEL-TYPE: D1	
TRANS	SFER DATE:		TYPE VERSION: F-111C	
RAAF TAIL	No: A8-1 3	39	USAF SERIAL NUMBER: A8-	-139
	RAAF AIRCI NSW (off co	RAFT. Aircraft no longer in the Raast) on 28 January 1986. Cause acted the water whilst flying a simu	AAF inventory - Crashed at Mo unknown. Lost at sea. ulated Harpoon profile.	
	RAAF AIRC NSW (off co A8-139 impa	RAFT. Aircraft no longer in the Raast) on 28 January 1986. Cause	AAF inventory - Crashed at Mo unknown. Lost at sea. ulated Harpoon profile. Killed	
	RAAF AIRCI NSW (off co A8-139 impa	RAFT. Aircraft no longer in the Raast) on 28 January 1986. Cause acted the water whilst flying a simu	AAF inventory - Crashed at Mo unknown. Lost at sea. ulated Harpoon profile. Killed	
NOTES:	RAAF AIRCI NSW (off co A8-139 impa	RAFT. Aircraft no longer in the Raast) on 28 January 1986. Cause acted the water whilst flying a simulating function of the second of the water	AAF inventory - Crashed at Mo unknown. Lost at sea. ulated Harpoon profile. Killed	
NOTES:	RAAF AIRCI NSW (off co A8-139 impa Pilot: Navigator: CRASHED:	RAFT. Aircraft no longer in the Raast) on 28 January 1986. Cause acted the water whilst flying a simulating function of the second of the water	AAF inventory - Crashed at Mo unknown. Lost at sea. ulated Harpoon profile. Killed	
NOTES:	RAAF AIRCI NSW (off co A8-139 impa Pilot: Navigator: CRASHED:	RAFT. Aircraft no longer in the Rast) on 28 January 1986. Cause acted the water whilst flying a simulation of the state of the water water water water water ERSKIN CPT Gregory Spence ANGELL 28/01/1986	AAF inventory - Crashed at Mo unknown. Lost at sea. ulated Harpoon profile. Killed	
NOTES: DATE	RAAF AIRCI NSW (off co A8-139 impa Pilot: Navigator: CRASHED: LOCATION:	RAFT. Aircraft no longer in the Rast) on 28 January 1986. Cause acted the water whilst flying a simulation of the state of the water water water water water ERSKIN CPT Gregory Spence ANGELL 28/01/1986	AAF inventory - Crashed at Mo unknown. Lost at sea. ulated Harpoon profile. Killed	
NOTES: DATE ROLL ACCEPTA	RAAF AIRCI NSW (off co A8-139 impa Pilot: Navigator: CRASHED: LOCATION:	RAFT. Aircraft no longer in the Rast) on 28 January 1986. Cause acted the water whilst flying a simulation of the state of the water water water water water ERSKIN CPT Gregory Spence ANGELL 28/01/1986	AAF inventory - Crashed at Mo unknown. Lost at sea. ulated Harpoon profile. Killed V GD S/N: 15	oruya,

RAAF TAIL I	no: A8-1 4	i1 ¹	JSAF SERIAL NUMBER: A8-141
NOTES:	26.5 nm from took off from air leak and f	n Whenuapai Island and near the p RNZAF Base, Ohakea on 25 Oct	AAF inventory - Crashed into the sea peninsular town of Coromandel. A/C ober, 1978. Crash was due to bleed rejected and survived the crash. The
			Killed
	Pilot:	WGCDR D.N. ROGERS	
	Navigator:	FLTLT P. GROWDER	
DATE	CRASHED:	25/10/1978	
	LOCATION:	Ohakea, NZ	
ROLL	OUT DATE:		GD S/N: 17
ACCEPTA	NCE DATE:		MODEL-TYPE: D1
TRANS	SFER DATE:		TYPE VERSION: F-111C
RAAF TAIL I	no: A8-1 4	.3	JSAF SERIAL NUMBER: A8-143
NOTES:	Aircraft suffe Both crew su Wheel on tak 1SQN Aircra Loss of Main	rrvived unhurt - they remained with keoff. ft Call sign COLT TWO	at Amberley RAAF Base on 18/7/06. In the aircraft. The aircraft lost a Main It taking the arrestor hook cable wheels beriod to PWD.
			Killed
	Pilot:	Flying Officer Peter Komar	
	Navigator:	Flight Lieutenant Luke Warner	
DATE	CRASHED:	18/07/2006	
	LOCATION:	AMBERLEY	
ROLL	OUT DATE:		GD S/N: 18
ACCEPTA	NCE DATE:		MODEL-TYPE: D1

RAAF TAIL NO: A8-291 USAF SERIAL NUMBER: 68-291

NOTES: Originally built for STRATEGIC AIR COMMAND (SAC).

Converted to F111G on 1/7/91.

This A/C was transferred to the RAAF inventory as A8-291.

The Aircraft crashed into Pulau Air Island (South China Sea) on 19 April 1999 during

exercises off Butterworth. Both the crew were killed.

The A/C was a 6SQN asset A/C AFHRS - 6340.5

Killed

Pilot: FLTLT Anthony SHORT ✓

Navigator: SQNLDR Stephen HOBBS ✓

DATE CRASHED: 19/04/1999

LOCATION: Pulau Air Island

ROLLOUT DATE: 11/08/1970 **GD S/N**: 63 **ACCEPTANCE DATE**: 30/01/1971 **MODEL-TYPE**: B1

TRANSFER DATE: 1/06/1991 TYPE VERSION: FB-111A